

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20

A B C D E F G H I J K L

SUDDERETH DRIVE

Sidewalk

Entry Drive

Staff Parking 8' x 20'

Property Line

Dumpsters

Note 1

All Exit Door Ramps to be inspected and reworked to be in compliance with 2009 A117.1.405.2. Maximum slope to be not more than 1 : 12 for all exposed edges.

REVIEWED FOR CODE COMPLIANCE BY THE VILLAGE OF RUIDOSO

See Note 1

FirePlace

See Note 1


Fire Lane

See Note 1

Existing Tree

See Note 1

Existing Fence



HandiCap

HandiCap

Existing Fence

Property Line

637 Suddereth



GRAYSON HARRIST
Architect - Contractor
806 - 543 - 7246

- 1 - All Work Shall Be Performed By Licenced Contractor And Meef Current Building And ADA Codes.
- 2 - Contractor To Verify Existing Site Conditions And Report Any Descrpancies Between The Drawings and Site Conditions To The Architech To Determine The Best Course Of Action. Any Work By The Contractor After Descrpancies Are Discovered Shall Be Done At Contractors Risk.
- 3 - Occupant Loads Listed Were Determined By Local Building Officials.
- 4 - Exit Sign Number And Location Were Inspected By Local Building Officials.
- 5 - All Structural Items Shall Be Engineered According To Local Building Codes And Conditions.
- 6 - Wall Mounted Fire Extingushers Shall Be Installed Per Current IBC.

Designed: SW	Date: NS	Scale: 2 of 10	Sheet: 2 of 10	Drawing No: A	Customer/Project: HMYP - Remodel
Revised Max Ramp Slope Released DISCUSSION BY DATE REV			Parking Plan Handicap and Staff		High Mountain Youth Project 637 Suddereth

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20